

Appendix of Photographs

Staniforth Road – Examples



Example of EWI on Staniforth Road, which is typical of the installations in this road.

Sill & head stones lost to 1st floor window
Stone Head over passageway lost (previously painted red)

Brick coursing detail lost (previously painted red)
Clumsy boxing around boiler vent and bay roof.

Paint overspill onto neighbouring house to disguise awkward box finish next to passage entrance. Also capping plastic clumsily left overhanging neighbouring house.



Staniforth Road – Shows contrast between EWI and traditional design but also shows how some houses were painted in the past.



Earl Marshal Road (below)

Shows contrast between traditional red brick and cream smooth render. Some Heads / Sills lost.

